


What's missing?? Penetrators, PMT Power supply components, pressure gauge, correct lead length for PMT pins, fiber...



Schematic view of DOM part layout